

LANCOM Release Notes

LANtools 10.50 RC3

Copyright © 2002-2021 LANCOM Systems GmbH, Wuerselen (Germany)

LANCOM Systems GmbH
Adenauerstrasse 20 / B2
52146 Wuerselen
Germany

Internet: <http://www.lancom-systems.com>

June 23rd, 2021, CBuersch

Table of Contents

1. Preface	2
2. New features, improvements, and history	3
LANconfig 10.50.0013 RC3	3
LANconfig 10.50.0010 RC2 / LANmonitor 10.50.0010 RC2	4
LANconfig 10.50.0008 RC1 / LANmonitor 10.50.0006 RC1	4
3. Important advice	5
Disclaimer	5

1. Preface

The LANtools are a comprehensive set of free management & monitoring tools for a detailed configuration and monitoring of LANCOM devices.

This document describes the innovations within LANtools version 10.50 RC3, as well as the improvements since the previous version.

Note

LANCOM LANtools support Microsoft Windows 7, Windows 8, Windows 10, Windows 2008 Server, Windows Small Business Server 2011, Windows Server 2012, Windows Server 2012 R2, Windows Server 2016, and Windows Server 2019 (all 32- and 64-bit versions).

For Windows Vista and Windows 2008 Server you will find user data under \Users\USER\AppData\Roaming\LANCOM\ and the application files under \ProgramData\LANCOM\.

When upgrading to LANtools 8.50 or newer, all existing user- and application data is moved to the corresponding folders.

2. New features, improvements, and history

LANconfig 10.50.0013 RC3

Bugfixes / improvements

LANconfig

- In the menu 'WLAN / 802.11u / Hotspot 2.0 Profile' the link to the table 'OSU providers' was missing. As a result, multiple selection of providers via selection dialog was not possible.
- In the Dynamic Path Selection (DPS) policies in the 'IP Router / Routing / SD-WAN Dynamic Path Selection (DPS) / Policies' menu, HTTP measurement profiles could not be selected.
- No maximum channel bandwidth of 160MHz could be selected in the access point profiles of a LANCOM WLC.

LANconfig 10.50.0010 RC2 / LANmonitor 10.50.0010 RC2

Bugfixes / improvements

LANconfig / LANmonitor

- > In the menu 'Wireless LAN / 802.1X / RADIUS servers' the selection dialog for specifying the protocol used was missing in the profile entry for a RADIUS server.
- > In LANmonitor, only the status code "144" was displayed when a volume budget value of 80% was reached.

LANconfig 10.50.0008 RC1 / LANmonitor 10.50.0006 RC1

New features

LANconfig / LANmonitor

- > Support for LCOS 10.50

3. Important advice

Disclaimer

LANCOM Systems GmbH does not take any guarantee and liability for software not developed, manufactured or distributed by LANCOM Systems GmbH, especially not for shareware and other extraneous software.